# Mainely Urns
& Memorials

Assembly Guide | Cremation Containers

1 First, lay the cardboard flat on a hard surface, patterned side facing down.

2 Take the side flaps closest to the curved edge and separate them along the perforated lines.

3 Fold the side flaps up and over the rectangle adjacent to the curved edge.

4 Holding the side flaps in place, bring the rest of the box up and over, fold in place.

5 Push the panels furthest from the curved edge into the box, tucking for stability.

6 Fold the open side flaps into the box, tamping down for stability.

7 Fold the curved edge along its perforated lines.

8 Bring open side down, tucking curved tabs in between the panels.